

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX

75 Hawthorne Street San Francisco, CA 94105

Certified Mail No 7001 0360 0000 3639 6747
Return Receipt Requested

AUG 2 8 2003

In Reply Refer to: WST-3

Mr. Earl Clinkenbeard, PE Engineering Specialist Pechiney Cast Plate P.O. Box 58447 Vernon, CA 90058

Re: Certification of Violation Correction for Pechiney Cast Plate, of Vernon, CA

Dear Mr. Clinkenbeard:

On March 26-27, 2003, a hazardous waste investigation was conducted by representatives of the United States Environmental Protection Agency ("EPA") at Pechiney Cast Plate, located at 3200 Fruitland Avenue, Vernon, CA, EPA Identification Number CAR 000 052 142. During the course of this investigation, information was gathered in accordance with Section 3007 of the Resource Conservation and Recovery Act ("RCRA"), as amended [42 U.S.C. 6927].

Pursuant to Section 3008 of RCRA [42 U.S.C. 6928], EPA required you to correct the identified areas of noncompliance and to submit documentation of their correction to the EPA within 30 days from the date the June 30, 2003, Warning Letter and inspection report were received.

Pechiney Cast Plate's submittal, dated July 29, 2003, adequately addresses the federal violations which were noted during the inspection, and documents Pechiney Cast Plate's return to compliance with the federal regulations cited in the inspection report. This letter should not be construed as a determination by EPA of your compliance with any and all other applicable regulations.

Pechiney Cast Plate should continue to take the necessary steps to maintain and ensure compliance with all applicable Federal, State and local environmental requirements. If you have

questions related to technical aspects of the investigation report or this letter, please contact Robin Holloway at (415) 972-3305.

Sincerely,

Frances Schultz, Manager RCRA Enforcement Office

Charles McLaughlin, Branch Chief State Regulatory Programs Division Department of Toxic Substances Control 8800 Cal Center Drive Sacramento, CA 95826-3200

7001 0360 0000 3639 6747 som Bochiney City, State, ZIP+ 4 Street, Apt. No.; or PO Box No. PS Form 3800, January 2001 Restricted Delivery Fee (Endorsement Required) Return Receipt Fee (Endorsement Required) Total Postage & Fees U.S. Postal Service
CERTIFIED MAIL RECEIPT (Domestic Mail Only; No Insurance Coverage Provided) Certified Fee Postage ₩. 69 40025 Mg A 90058
See Reverse for Instructions Postmark Here

14 - 1005 214 : 3A-1



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX 75 Hawthorne Street

75 Hawthorne Street San Francisco, CA 94105

Certified Mail No 7001 0360 0000 3639 6747 Return Receipt Requested

In Reply Refer to: WST-3

AUG 2 8 2003

Mr. Earl Clinkenbeard, PE Engineering Specialist Pechiney Cast Plate P.O. Box 58447 Vernon, CA 90058

Re: Certification of Violation Correction for Pechiney Cast Plate, of Vernon, CA

Dear Mr. Clinkenbeard:

On March 26-27, 2003, a hazardous waste investigation was conducted by representatives of the United States Environmental Protection Agency ("EPA") at Pechiney Cast Plate, located at 3200 Fruitland Avenue, Vernon, CA, EPA Identification Number CAR 000 052 142. During the course of this investigation, information was gathered in accordance with Section 3007 of the Resource Conservation and Recovery Act ("RCRA"), as amended [42 U.S.C. 6927].

Pursuant to Section 3008 of RCRA [42 U.S.C. 6928], EPA required you to correct the identified areas of noncompliance and to submit documentation of their correction to the EPA within 30 days from the date the June 30, 2003, Warning Letter and inspection report were received.

Pechiney Cast Plate's submittal, dated July 29, 2003, adequately addresses the federal violations which were noted during the inspection, and documents Pechiney Cast Plate's return to compliance with the federal regulations cited in the inspection report. This letter should not be construed as a determination by EPA of your compliance with any and all other applicable regulations.

Pechiney Cast Plate should continue to take the necessary steps to maintain and ensure compliance with all applicable Federal, State and local environmental requirements. If you have

questions related to technical aspects of the investigation report or this letter, please contact Robin Holloway at (415) 972-3305.

Sincerely,

Frances Schultz, Manager RCRA Enforcement Office

cc:

Charles McLaughlin, Branch Chief State Regulatory Programs Division Department of Toxic Substances Control 8800 Cal Center Drive Sacramento, CA 95826-3200



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX

75 Hawthorne Street San Francisco, CA 94105

> <u>Certified Mail No.</u> Return Receipt Requested

In Reply Refer to: WST-3

Mr. Earl Clinkenbeard, PE Engineering Specialist Pechiney Cast Plate P.O. Box 58447 Vernon, CA 90058

Re: Certification of Violation Correction for Pechiney Cast Plate, of Vernon, CA

Dear Mr. Clinkenbeard:

On March 26-27, 2003, a hazardous waste investigation was conducted by representatives of the United States Environmental Protection Agency ("EPA") at Pechiney Cast Plate, located at 3200 Fruitland Avenue, Vernon, CA, EPA Identification Number CAR 000 052 142. During the course of this investigation, information was gathered in accordance with Section 3007 of the Resource Conservation and Recovery Act ("RCRA"), as amended [42 U.S.C. 6927].

Pursuant to Section 3008 of RCRA [42 U.S.C. 6928], EPA required you to correct the identified areas of noncompliance and to submit documentation of their correction to the EPA within 30 days from the date the June 30, 2003, Warning Letter and inspection report were received.

Pechiney Cast Plate's submittal, dated July 29, 2003, adequately addresses the federal violations which were noted during the inspection, and documents Pechiney Cast Plate's return to compliance with the federal regulations cited in the inspection report. This letter should not be

MAIL CODE	W57 3	WST3	W51,3		
SURNAME	Hollower	G Lan	Schutt		
	8-1-03	8/7/03	8/27/03		

U.S. EPA CONCURRENCES

OFFICIAL FILE COPY

construed as a determination by EPA of your compliance with any and all other applicable regulations.

Pechiney Cast Plate should continue to take the necessary steps to maintain and ensure compliance with all applicable Federal, State and local environmental requirements. If you have questions related to technical aspects of the investigation report or this letter, please contact Robin Holloway at (415) 972-3305.

Sincerely,

Frances Schultz, Manager RCRA Enforcement Office

cc:

Charles McLaughlin, Branch Chief State Regulatory Programs Division Department of Toxic Substances Control 8800 Cal Center Drive Sacramento, CA 95826-3200